








Model	X1	X2	H
Walk-In 50	485-493	max 1500	2000
Walk-In 55	535-543	max 1500	2000
Walk-In 60	585-593	max 1500	2000
Walk-In 65	635-643	max 1500	2000
Walk-In 70	685-693	max 1500	2000
Walk-In 75	735-743	max 1500	2000
Walk-In 80	785-793	max 1500	2000
Walk-In 85	835-843	max 1500	2000
Walk-In 90	885-893	max 1500	2000
Walk-In 95	935-943	max 1500	2000
Walk-In 100	985-993	max 1500	2000
Walk-In 105	1035-1043	max 1500	2000
Walk-In 110	1085-1093	max 1500	2000
Walk-In 115	1135-1143	max 1500	2000
Walk-In 120	1185-1193	max 1500	2000
Walk-In 125	1235-1243	max 1500	2000
Walk-In 130	1285-1293	max 1500	2000

Model	X1	X2	H
Walk-In 135	1335-1343	max 1500	2000
Walk-In 140	1385-1393	max 1500	2000
Walk-In 145	1435-1443	max 1500	2000
Walk-In 150	1485-1493	max 1500	2000
Walk-In 155	1535-1543	max 1500	2000
Walk-In 160	1585-1593	max 1500	2000